

Ref #	Hits	Search Query	DBs	Default Operator	Plurals	Time Stamp
L1	8	(thread\$4 near4 (determin\$4 detect\$4 asses\$4 estimat\$4 monitor\$4 sens\$4 meter\$4 observ\$4 gaug\$4 measur\$4) near4 (wear\$4 worn fatigue shear\$4 decay scratch\$4)) .clm.	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2004/12/03 15:46
L2	86	(thread\$4 near3 (determin\$4 detect\$4 asses\$4 estimat\$4 monitor\$4 sens\$4 meter\$4 observ\$4 gaug\$4 measur\$4) near3 (wear\$4 worn fatigue shear\$4 decay scratch\$4))	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2004/12/03 15:48
S1	100	73/811.ccls.	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2004/12/02 16:41
S2	295	73/856.ccls.	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2004/12/03 13:15
S3	84	73/859.ccls.	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2004/12/03 13:36
S4	112	("5490333" "4334438" "4888151" "4993864" "4974165" "4906151" "4331410" "4258836" "5785109" "5024623" "4333307" "4417402" "5564173" "3845564" "4347051" "5551259" "6401793" "5234385" "4433590" "4433817" "4825786" "5303464" "5804905" "4566500" "4630651" "4256421" "4315708" "4325665" "4599021" "5799917" "6312393" "6321667" "5521707" "5712706" "4356636" "4858330" "6147318" "4300265" "4493478" "6099081" "6176445" "4245792" "4252201" "4307666" "4475575" "4527039" "4579203" "4761868" "4778730" "4784245").pn.	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2004/12/03 11:38
S5	655	33/199R.ccls.	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2004/12/03 15:00
S6	2	((stencil pattern frame reference mold model) near4 thread\$4 near4 (determin\$4 asses\$4 estimat\$4 monitor\$4 sens\$4 meter\$4 observ\$4 measur\$4) near4 (wear\$4 worn fatigue decay scratch\$4))	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2004/12/03 13:49
S7	3	((stencil pattern frame reference mold model) near4 (undulate\$3 thread\$4 wavy wedg\$4) near4 (determin\$4 asses\$4 estimat\$4 monitor\$4 sens\$4 meter\$4 observ\$4 measur\$4) near4 (wear\$4 worn fatigue decay scratch\$4))	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2004/12/03 13:52
S8	83	((undulate\$3 thread\$4 wavy wedg\$4) near4 (determin\$4 asses\$4 estimat\$4 monitor\$4 sens\$4 meter\$4 observ\$4 measur\$4) near4 (wear\$4 worn fatigue decay scratch\$4))	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2004/12/03 14:09
S9	126	((undulate\$3 thread\$4 wavy wedg\$4) near4 (determin\$4 asses\$4 estimat\$4 monitor\$4 sens\$4 meter\$4 observ\$4 measur\$4) near4 (wear\$4 worn fatigue shear\$4 decay scratch\$4))	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2004/12/03 14:14
S10	150	((undulate\$3 thread\$4 wavy wedg\$4) near4 (determin\$4 detect\$4 asses\$4 estimat\$4 monitor\$4 sens\$4 meter\$4 observ\$4 measur\$4) near4 (wear\$4 worn fatigue shear\$4 decay scratch\$4))	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2004/12/03 15:43

S11	25	((template) near4 (determin\$4 detect\$4 asses\$4 estimat\$4 monitor\$4 sens\$4 meter\$4 observ\$4 measur\$4) near4 (wear\$4 worn fatigue shear\$4 decay scratch\$4))	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2004/12/03 14:25
S12	4	("2731730" "3193936").PN	US-PGPUB; USPAT; USOCR	OR	ON	2004/12/03 14:31
S13	5	("4185391").URPN.	USPAT	OR	ON	2004/12/03 14:37
S14	17	("2731730" "3193936" "3603650" "3606497" "3805761" "3907382" "3960412" "4059022" "4185391" "4276040" "4443041" "4487088" "4776826" "5144762").PN	US-PGPUB; USPAT; USOCR	OR	ON	2004/12/03 14:39
S15	2	("5348515").URPN.	USPAT	OR	ON	2004/12/03 14:42
S16	17	("1426956" "1913564" "3678883" "3897116" "3922999" "4322966" "4576499" "4650441" "5348515" "5451110" "5540448" "5718633" "5978500" "6178824" "6289735").PN	US-PGPUB; USPAT; USOCR	OR	ON	2004/12/03 14:43
S17	91	33/501.7.ccls.	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2004/12/03 15:00
S18	1	("2819532").URPN	USPAT	OR	ON	2004/12/03 15:10
S19	2	("2731730" "3193936").pn.	USPAT	OR	ON	2004/12/03 15:10